

# Basic Kripke Shipping Specs Toledo Plant

---

## **General Packaging**

### **Boxed Material**

1. If boxes are double stacked, heavier box must be on bottom and top box can not fall into bottom.
2. It is suggested that each box has a strap around the middle of the box.
3. It is suggested that each box be strapped to skids.
4. No boxes soaked through with grease, oil, or any other fluid.
5. All scrap must be dry.
6. Material must be completely free of iron, UBC's, and other contaminates.
7. Absolutely no crimped pipe.

### **Skidded Material**

1. All material must be strapped to the skid both north-south, and east-west.
2. Material must be stack in an orderly fashion.
3. Material must be segregated by alloy.
4. All scrap must be dry.
5. Material must be completely free of iron, UBC's, and other contaminates.
6. Absolutely no crimped pipe.

### **Baled Material**

1. Bales must be stacked no more than three high.
2. All stacks of bales must be on skids.
3. All scrap must be dry.
4. Material must be completely free of iron, beverage cans, and other contaminates.
5. Absolutely no crimped pipe.

## **Specific Items**

### **356 Auto Wheels**

1. All wheels must be free of iron inserts, valve stems, and chrome.
2. It is suggested that wheels be packed 54 wheels to a skid, 9 rows of 6 high. A 44"x44" pallet with no wings works the best for this.
3. Wheels must be adequately shrink wrapped so they are stable for loading and unloading. A band around the middle of the pallet is preferred.
4. When double stacking top pallet must have bottom runners.
5. All wheels must be free of grease and any liquid of any kind.

### **6061 Truck Wheels**

1. All wheels must be free of grease, valve stems, and any liquid of any kind.
2. It is suggested that wheels be packed 16 to a pallet, 4 rows of 4 high. A 44" x 44" pallet with no wings works best for this.
3. Wheels must be adequately shrink wrapped so they are stable for loading and unloading. A band around the middle of the pallet is preferred.
4. When double stacking top pallet must have bottom runners.